

GRINNELL CASE FILE

Putting more “in the pipeline” for you

Tiara Condominium

Singer Island, Florida



Copper Grooved System



Copper Grooved System

MARKET:

Plumbing

COMPLETED:

12/1/07

DISTRIBUTOR:

Gainesville Windustrial

CONTRACTOR:

P.C.A.

SPECIFICATIONS:

4" 672 Couplings

Copper Fittings

B680 Butterfly Valves

GRINNELL SOLUTIONS:

Tiara is a 30 year old condo that sustained substantial damage during Hurricane Wilma in 2006. The owners decided to do a total retrofit of all mechanical piping and equipment in the building. Due to the low ceilings and odd building design angles the Grinnell mechanical grooved system was perfect to accommodate the tight spaces and dimensional challenges.



Tiara Condominium

tyco

Fire Suppression
& Building Products



Grinnell[®]
MECHANICAL SERVICES

GRINNELL CASE FILE

Putting more "in the pipeline" for you

Tiara Condominium

Singer Island, Florida



Copper Grooved System



Copper Grooved System



Grinnell®

MECHANICAL SERVICES

CUSTOMER SERVICE

800-558-5236

TECHNICAL SERVICES

866-500-4768

www.grinnell.com



tyco

Fire Suppression
& Building Products

© 2008 Tyco Fire & Building Products.